



Tolerance -8%/+2% -8%/+2% -8%/+2% -8%/+2% 0/+10%

D mm	L mm	L2 mm	W mm	W1 mm
6	66	15	15	12
8	88	20	20	16
10	110	25	25	20